



March 2019

Recertification requirements for 3.2A/10, /15 and /20 Driver Suits

The SFI Spec for Driver Suits states that all jacket and pants or driver suits that meet the SFI Spec 3.2A/10 or higher must be recertified on a five-year interval.

Suits with these higher ratings have SFI patches that indicate the year of manufacture or the year of the last recertification on them.

(<u>Please be aware that the five-year recertification period includes the year displayed on the patch</u>)

Below are the recertification dates for the different year patches currently available:

SFI Patch Insignia
Recertification Time Frame

No date patch

Certification expired on 31. Dec. 2004

2014 date patch

Certification expired on 31. Dec. 2018

2015 date patch

Certification expires on 31. Dec. 2019

2016 date patch

Certification expires on 31. Dec. 2020

2017 date patch

Certification expires on 31. Dec. 2021

2018 date patch

Certification expires on 31. Dec. 2022

2019 date patch

Certification expires on 31. Dec. 2023

For recertification, owners of driver suits should contact the original manufacturer to be informed about their procedures for returning the suits for inspection and recertification.

On driver suits with sewn-in arm restraints, the date stamped on the arm restraints is a reference date for the manufacturer and has no bearing on the suit's expiration date.

Sincerely yours

